



Photo 1: Culvert inlet and road embankment.

|                                                                                                                           |                                  |                              |                           |
|---------------------------------------------------------------------------------------------------------------------------|----------------------------------|------------------------------|---------------------------|
| REPORT TITLE<br><b>Civil Engineering Site Review</b><br><br>PROJECT DESCRIPTION<br>Culvert, drainage and concrete details | PROJECT NO.<br>ENG-26067         | CLIENT<br>Example Properties | SITE<br>Brookside Culvert |
|                                                                                                                           | DATE<br>2026-09-09               | PREPARED<br>A. Morgan        | CHECKED<br>J. Lee         |
|                                                                                                                           | COMPANY<br>Fieldstone Consulting |                              | SHEET<br><b>1 of 4</b>    |



Photo 2: Concrete wingwall joint condition.



Photo 3: Downstream channel and erosion protection.



Photo 4: Roadside guardrail and support posts.



Photo 5: Localized concrete surface deterioration.



Photo 6: Catch basin at the curb.



Photo 7: Retaining wall drainage outlet.

|                                                                                                                           |                                  |                              |                           |
|---------------------------------------------------------------------------------------------------------------------------|----------------------------------|------------------------------|---------------------------|
| REPORT TITLE<br><b>Civil Engineering Site Review</b><br><br>PROJECT DESCRIPTION<br>Culvert, drainage and concrete details | PROJECT NO.<br>ENG-26067         | CLIENT<br>Example Properties | SITE<br>Brookside Culvert |
|                                                                                                                           | DATE<br>2026-09-09               | PREPARED<br>A. Morgan        | CHECKED<br>J. Lee         |
|                                                                                                                           | COMPANY<br>Fieldstone Consulting |                              | SHEET<br><b>2 of 4</b>    |



Photo 8: Pedestrian path beside the channel.




Photo 9: Headwall and adjacent grass slope.

|                                                                                                                                                         |                                                 |                                             |                                          |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|---------------------------------------------|------------------------------------------|
| <small>REPORT TITLE</small><br><b>Civil Engineering Site Review</b><br><br><small>PROJECT DESCRIPTION</small><br>Culvert, drainage and concrete details | <small>PROJECT NO.</small><br>ENG-26067         | <small>CLIENT</small><br>Example Properties | <small>SITE</small><br>Brookside Culvert |
|                                                                                                                                                         | <small>DATE</small><br>2026-09-09               | <small>PREPARED</small><br>A. Morgan        | <small>CHECKED</small><br>J. Lee         |
|                                                                                                                                                         | <small>COMPANY</small><br>Fieldstone Consulting |                                             | <small>SHEET</small><br><b>3 of 4</b>    |



Photo 10: Sediment at the channel bend.



Photo 11: Expansion joint sealant condition.

|                                                                                                                                                   |                                                     |                                                 |                                              |
|---------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|-------------------------------------------------|----------------------------------------------|
| <div>REPORT TITLE</div> <div>Civil Engineering Site Review</div> <div>PROJECT DESCRIPTION</div> <div>Culvert, drainage and concrete details</div> | <div>PROJECT NO.</div> <div>ENG-26067</div>         | <div>CLIENT</div> <div>Example Properties</div> | <div>SITE</div> <div>Brookside Culvert</div> |
|                                                                                                                                                   | <div>DATE</div> <div>2026-09-09</div>               | <div>PREPARED</div> <div>A. Morgan</div>        | <div>CHECKED</div> <div>J. Lee</div>         |
|                                                                                                                                                   | <div>COMPANY</div> <div>Fieldstone Consulting</div> |                                                 | <div>SHEET</div> <div>4 of 4</div>           |