



Photo 1: Aboveground fuel tank beside the maintenance building.

REPORT TITLE Phase I ESA Site Review PROJECT DESCRIPTION Site reconnaissance and storage areas	PROJECT NO. ESA-26041	CLIENT Example Properties	SITE Riverview Works
	DATE 2026-09-09	PREPARED A. Morgan	CHECKED J. Lee
	COMPANY Fieldstone Consulting		SHEET 1 of 4



Photo 2: Drum storage on a containment pallet.



Photo 3: Capped service connections at the former equipment pad.



Photo 4: Surface drainage along the property boundary.



Photo 5: Concrete condition in the vehicle maintenance bay.

REPORT TITLE Phase I ESA Site Review PROJECT DESCRIPTION Site reconnaissance and storage areas	PROJECT NO. ESA-26041	CLIENT Example Properties	SITE Riverview Works
	DATE 2026-09-09	PREPARED A. Morgan	CHECKED J. Lee
	COMPANY Fieldstone Consulting		SHEET 2 of 4



Photo 6: Catch basin in the paved service yard.



Photo 7: Electrical transformer enclosure.

REPORT TITLE Phase I ESA Site Review PROJECT DESCRIPTION Site reconnaissance and storage areas	PROJECT NO. ESA-26041	CLIENT Example Properties	SITE Riverview Works
	DATE 2026-09-09	PREPARED A. Morgan	CHECKED J. Lee
	COMPANY Fieldstone Consulting		SHEET 3 of 4



Photo 8: Loading dock and waste storage area.



Photo 9: Workshop storage cabinet.

REPORT TITLE Phase I ESA Site Review PROJECT DESCRIPTION Site reconnaissance and storage areas	PROJECT NO. ESA-26041	CLIENT Example Properties	SITE Riverview Works
	DATE 2026-09-09	PREPARED A. Morgan	CHECKED J. Lee
	COMPANY Fieldstone Consulting		SHEET 4 of 4