



Photo 1: Monitoring well MW-01 and protective casing.



Photo 2: Flush-mount well MW-02 in the service yard.



Photo 3: Groundwater sampling setup at MW-03.



Photo 4: Recovered soil core from borehole BH-04.



Photo 5: Soil sample containers prepared for transport.



Photo 6: Completed borehole location following reinstatement.

REPORT TITLE Groundwater & Soil Monitoring PROJECT DESCRIPTION Field observations - Illustrative sample	PROJECT NO. ENV-26058	CLIENT Example Properties	SITE Meadowbrook Monitoring Site
	DATE 2026-06-22	PREPARED A. Morgan	CHECKED J. Lee
	COMPANY Fieldstone Environmental		SHEET 1 of 1