



Photo 1: Front elevation and pedestrian approach.



Photo 2: Damaged siding at the building corner.



Photo 3: Downspout discharge beside the foundation.



Photo 4: Vertical crack in the basement wall.

REPORT TITLE Property Condition Survey PROJECT DESCRIPTION Exterior and interior condition record	PROJECT NO. PCI-26032	CLIENT Example Properties	SITE Maple Court House
	DATE 2026-09-09	PREPARED A. Morgan	
	COMPANY Fieldstone Consulting	SHEET 1 of 4	



Photo 5: Ceiling staining above the bedroom window.



Photo 6: Window perimeter sealant condition.

REPORT TITLE Property Condition Survey PROJECT DESCRIPTION Exterior and interior condition record	PROJECT NO. PCI-26032	CLIENT Example Properties	SITE Maple Court House
	DATE 2026-09-09	PREPARED A. Morgan	
	COMPANY Fieldstone Consulting	SHEET 2 of 4	



Photo 7: Concrete entry step condition.

REPORT TITLE Property Condition Survey PROJECT DESCRIPTION Exterior and interior condition record	PROJECT NO. PCI-26032	CLIENT Example Properties	SITE Maple Court House
	DATE 2026-09-09		PREPARED A. Morgan
	COMPANY Fieldstone Consulting		SHEET 3 of 4



Photo 8: Basement floor drain.



Photo 9: Weathering on the deck railing.

REPORT TITLE Property Condition Survey PROJECT DESCRIPTION Exterior and interior condition record	PROJECT NO. PCI-26032	CLIENT Example Properties	SITE Maple Court House
	DATE 2026-09-09	PREPARED A. Morgan	
	COMPANY Fieldstone Consulting	SHEET 4 of 4	