



Photo 1: Overview of the roof and chimney.



Photo 2: Lifted shingle edge and granule loss.

REPORT TITLE Roof Condition Survey PROJECT DESCRIPTION Roof covering and drainage details	PROJECT NO. ROOF-26019	CLIENT Example Properties	SITE Cedar Lane House
	DATE 2026-09-09	COMPANY Fieldstone Consulting	SHEET 1 of 4



Photo 3: Weathered flashing boot at the roof vent.

REPORT TITLE Roof Condition Survey PROJECT DESCRIPTION Roof covering and drainage details	PROJECT NO. ROOF-26019	CLIENT Example Properties	SITE Cedar Lane House
	DATE 2026-09-09	COMPANY Fieldstone Consulting	SHEET 2 of 4



Photo 4: Debris in the gutter near the outlet.



Photo 5: Step flashing at the chimney.



Photo 6: Condition of the ridge shingles.



Photo 7: Roof valley and intersecting slopes.

REPORT TITLE Roof Condition Survey PROJECT DESCRIPTION Roof covering and drainage details	PROJECT NO. ROOF-26019	CLIENT Example Properties	SITE Cedar Lane House
	DATE 2026-09-09	COMPANY Fieldstone Consulting	SHEET 3 of 4



Photo 8: Drip edge and fascia detail.



Photo 9: Moss along the shaded roof edge.

REPORT TITLE Roof Condition Survey PROJECT DESCRIPTION Roof covering and drainage details	PROJECT NO. ROOF-26019	CLIENT Example Properties	SITE Cedar Lane House
	DATE 2026-09-09	COMPANY Fieldstone Consulting	SHEET 4 of 4